



DIRECCIÓN NACIONAL DE AERONAVEGABILIDAD (DNA)
DIRECCIÓN AVIACIÓN GENERAL (DAG)
REPÚBLICA ARGENTINA

ADVERTENCIA 081/DAG

La presente ADVERTENCIA tiene por objeto dar a conocer una situación que puede resultar de interés para Talleres Aeronáuticos de Reparación, operadores y/o propietarios de aeronaves. Se emite a los efectos de informar y las recomendaciones no tienen carácter mandatorio.

Ciudad Autónoma de Buenos Aires, 17 de enero de 2008.

APLICABLE A: Aeronaves Piper PA-23, PA-31, PA-31P, PA-31T y PA-42 Series.

MOTIVO: Posibilidad de falla de manguera hidráulica del tren de aterrizaje.

ANTECEDENTES: Esta Advertencia pone en conocimiento del público usuario del Special Airworthiness Information Bulletin (SAIB) N° CE-08-11 de fecha 09-Enero-2008, emitido por la Federal Aviation Administration de EE.UU., relacionado con la falla de la manguera hidráulica P/N 17766-02 (465-138), que podría provocar la pérdida de la presión necesaria para extender el tren de aterrizaje.

Se adjunta a esta Advertencia el SAIB N° CE-08-11 (dos páginas).

RECOMENDACION: Esta Dirección recomienda la inspección de las mangueras hidráulicas del tren de aterrizaje P/N 17766-02 (465-138) por pérdidas y signos de deterioro y, en caso de encontrar novedades, el reemplazo de la parte afectada antes del próximo vuelo, de acuerdo al párrafo "*Recommendations*" del SAIB N° CE-08-11.

Para obtener mayor información dirigirse a la División Ingeniería de la DAG:

Tel.: (011) 4508-2105

Fax: (011) 4576-6404

E-mail: av.general@fibertel.com.ar

Página Web: www.dna.org.ar

Comodoro Claudio M. Movilla
Subdirector Nacional de Aeronavegabilidad



SUBJ: Landing Gear

This is information only. Recommendations aren't mandatory.

Introduction

This Special Airworthiness Information Bulletin (SAIB) alerts you of an airworthiness concern on the following The New Piper Aircraft, Inc. (Piper) airplanes (**Table 1**) regarding potential failure of hydraulic hose part number (P/N) 17766-02 (465-138). The failure of the hydraulic hose may result in loss of pressure to extend the landing gears:

Table 1

Models	Serial Numbers
PA-23	All serial numbers
PA-23 -150/160/235/250	All serial numbers
PA31	All serial numbers
PA31-300/310/325/350	All serial numbers
PA-31P	All serial numbers
PA-31P-350	All serial numbers
PA31-350 T1020	All serial numbers
PA31T Cheyenne	All serial numbers
PA31T Cheyenne II	All serial numbers
PA31T1 Cheyenne I	All serial numbers
PA31T1 Cheyenne IA	All serial numbers
PA31T2 Cheyenne IIXL	All serial numbers
PA31T3 T1040	All serial numbers
PA-42 Cheyenne III	All serial numbers
PA-42 Cheyenne IIIA	All serial numbers

Background

This SAIB is a result of FAA Accident Prevention Recommendations (APR) 07.097. This APR reported an incident on a Piper Model PA-31T airplane that occurred during an emergency landing. The airplane landed with the right main down along with the nose and left main gears retracted, which caused damage to the airplane engines, propellers, belly skin, and nose skin of the airplane.

The investigation revealed that the left main landing gear hydraulic pressure hose, P/N 17766-2 (465-138), which was located in the left main landing gear well, had ruptured. This hydraulic hose had deteriorated through years in-service. The hose was installed in March 1979 and had accumulated a total of 6,349 hours time-in-service.

Recommendations

We recommend that you inspect the landing gear hydraulic hose, P/N 17766-2 (465-138), for leaks and signs of deterioration. If there is evidence of leaks or signs of deterioration in the hydraulic hose, we recommend that you replace the part before further flight.

For Further Information Contact

Hector Hernandez, Aerospace Engineer, FAA, Central Region, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, GA 30349; phone (770) 703-6069; fax (770) 703-6097; email: Hector.Hernandez@faa.gov